Culebra Landfill, Puerto Rico Inspection Photo Album



17 SEPTEMBER 2014





































Discarded refrigerators (CFCs) and other white goods along entrance road to the Culebra Landfill.





























Top of Landfill, looking panoramically.










Green/yard waste in landfill.







landfill overlooking Caribbean Sea. View is of slope profile, looking north by northwest.












Operator not present at Culebra Landfill while it was receiving waste.

Uncovered waste.







Southwestern slope of landfill (slope= n:1).



















EPA Inspector along beach approaching the western base of Landfill.





Beach area to the south southwest of the landfill.

























Northwest of Landfill (Landfill to the right of image).



Northwest corner of Landfill. Note: dumping at base of slope.

